



# Mojust Global Resources Ltd RC 808075

## OFFICE ADDRESS:

10 Hon. Gideon Street off Peter Odili Road Trans-Amadi, Port Harcourt. Tel: 08035593796, 08075694479

E-mail: info@mojustglobal.com, [mojustglobalresources@gmail.com](mailto:mojustglobalresources@gmail.com) Website: [www.mojustglobal.com](http://www.mojustglobal.com)



## CERTIFICATE OF VISUAL EXAMINATION

Client	CAVMONT LEASING NIGERIA LTD	CERTIFICATE NO.	CB/01-15/002
Equipment Owner/ Address	CAVMONT LEASING NIG LTD. PLOT 274 TRANS-AMADI, PORT HARCOURT	INSPECTOR QUALIFICATION	NIGERIA FACTORY ACT/ASNT LEVEL II, NSL
Location	CAVMONT BASE		
Inspection Date	29/01/2015	Next Inspection Date	28/07/2015

Description	12FT CARGO BASKET
Size (Metres)	LENGTH: 3.66m WIDTH: 1.21m HEIGHT: 1.22m
Equipment Identification	CB3-020
Tare Weight	1070Kg
Pay Load	7500Kg
Maximum Gross Weight	8570Kg

S/N	Item ID No.	Qty	Items Description	SWL	Remark/Recommendation
1	Sling#: CB3-20A	1	4Legs Wire Rope Sling 22mm dia. x 2.5m fitted with Quad Master Link Assembly at one end, c/w thimble eye on both end.	9.0 Tonne @ 0-45°	Certified fit for Use
2	Shackle#: 20A/1, 20A/2, 20A/3, 20A/4.	4	Safety Pin Bow Shackle (BS)	8.5 Tons	Certified fit for Use

### LOAD TEST DETAIL

UNIT	Tested By: LLOYD'S REGISTER	Certificate No: 230055	Test Date: 02/08
Sling	Tested By: UNIVERSAL INSPECTION LTD.(UIL)	Certificate No: 119693/20	Test Date: 13/11/08

SPECIFICATION: DNV 2.7-1, BS EN13414-2, BS 13889	Equipment Type: N/A	Test Procedure: MG 53
NDT METHOD: Visual Inspection		Contrast Media: N/A
RESULTS: At the time of examination, no cracks, flaws or other defects likely to affect the safe use of the equipment was found. Ok for use	Pole Spacing: N/A	Indicator: Black N/A
STATUTORY INSTRUMENTS 1998 NO.2307. Lifting Operations and Lifting Equip. Regulation 1998. British Standard: DNV 2.7-1		

Signature of inspector:



Name of inspector: EMEKA JUDE