



# Mojust Global Resources Ltd RC 808075

## OFFICE ADDRESS:

10 Hon. Gideon Street off Peter Odili Road Trans-Amadi, Port Harcourt. Tel: 08035593796, 08075694465

E-mail: [info@mojustglobal.com](mailto:info@mojustglobal.com), [mojustglobalresources@gmail.com](mailto:mojustglobalresources@gmail.com) Website: [www.mojustglobal.com](http://www.mojustglobal.com)



## CERTIFICATE OF VISUAL EXAMINATION

Client	CAVMONT LEASING NIGERIA LTD	CERTIFICATE NO.	GTF/11-14/345
Equipment Owner/ Address	CAVMONT LEASING NIG LTD. PLOT 274 TRANS-AMADI, PORT HARCOURT	INSPECTOR QUALIFICATION	NIGERIA FACTORY ACT/ASNT LEVEL II, NSL
Location	CAVMONT BASE		
Inspection Date	20/11/2014	Next Inspection Date	19/05/2015

Description	600 GALLON TANK FRAME
Size (Metres)	LENGTH: 2.03m WIDTH: 2.03m HEIGHT: 1.60m
Equipment Identification	ST 825
Tare Weight	2130Kg
Pay Load	4370Kg
Maximum Gross Weight	6500Kg

S/N	Item I.D No.	Qty	Items Description	SWL	Remark/Recommendation
1	Sling#: GL 12638/6	1	4Legs Wire Rope Sling 22mm dia. x 2.5m fitted with Quad Master Link Assembly at one end, c/w thimble eye on both end.	7.0 Tonne @ 0-45°	Certified fit for Use
2	Shackle#: 6/1, 6/2, 6/3, 6/4.	4	Safety Pin Bow Shackle (Crosby)	4.75 Tons	Certified fit for Use

### LOAD TEST DETAIL

UNIT	Tested By: DET NORSKE VERITAS(DNV)	Certificate No: 121675/121	Test Date: 05/06
Sling	Tested By: UNIVERSAL INSPECTION LTD.(UIL)	Certificate No: 126012/14	Test Date: 06/11

SPECIFICATION: DNV 2.7-1, BS EN13414-2, BS 13889	Equipment Type: N/A	Test Procedure: MG 53
NDT METHOD: Visual Inspection		Contrast Media: N/A
RESULTS: At the time of examination, no cracks, flaws or other defects likely to affect the safe use of the equipment was found. Ok for use	Pole Spacing: N/A	Indicator: Black N/A

STATUTORY INSTRUMENTS 1998 NO.2307.  
Lifting Operations and Lifting Equip. Regulation 1998. British Standard: DNV 2.7-1

Signature of inspector:

Name of inspector: ONOME OGBORU

