



# Mojust Global Resources Ltd RC 808075

## OFFICE ADDRESS:

10 Hon. Gideon Street off Peter Odili Road Trans-Amadi, Port Harcourt. Tel: 08035593796, 08075694465

E-mail: [info@mojustglobal.com](mailto:info@mojustglobal.com), [mojustglobalresources@gmail.com](mailto:mojustglobalresources@gmail.com) Website: [www.mojustglobal.com](http://www.mojustglobal.com)



## CERTIFICATE OF VISUAL EXAMINATION

Client	CAVMONT LEASING NIGERIA LTD	CERTIFICATE NO.	GCT/11-14/372
Equipment Owner/ Address	CAVMONT LEASING NIGERIA LTD, PLOT 274 TRANS-AMADI,PORT HARCOURT	INSPECTOR QUALIFICATION	NIGERIA FACTORY ACT/ASNT LEVEL II,NSL
Location	CAVMONT BASE		
Inspection Date	25/11/2014	Next Inspection Date	24/05/2015

Description	600 GALLON CHEMICAL TANK
Size (Metres)	LENGTH: 2.03m WIDTH: 2.03m HEIGHT:1.61m
Equipment Identification	ST 922
Tare Weight	2130Kg
Pay Load	4370Kg
Maximum Gross Weight	6500Kg

S/N	Item I.D No.	Qty	Items Description	SWL	Remark/Recommendation
1	Sling#: ST 922A	1	4Legs Wire Rope Sling 24mm dia. x 2.5m fitted with Quad Master Link Assembly at one end, c/w thimble eye on both end.	7.0 Tonnes @ 0-45°	Certified fit for Use
2	Shackle#: 22B, 22C, 22D, 22E.	4	Safety Pin Bow Shackle (Crosby)	4.75 Tons	Certified fit for Use

### LOAD TEST DETAIL

UNIT	Tested By: DET NORSKE VERITAS(DNV)	Certificate No:69823	Test Date: 03/07
Sling	Tested By: UNIVERSAL INSPECTION LTD(UIL)	Certificate No:126672/15	Test Date: 12/11

SPECIFICATION: DNV 2.7-1, BS EN13414-2, BS 13889	Equipment Type: N/A	Test Procedure: MG 53
NDT METHOD: Visual Inspection		
RESULTS: At the time of examination, no cracks, flaws or other defects likely to affect the safe use of the equipment was found. Ok for use	Pole Spacing: N/A	Contrast Media: N/A
		Indicator: Black N/A
STATUTORY INSTRUMENTS 1998 NO.2307. Lifting Operations and Lifting Equip. Regulation 1998. British Standard: DNV 2.7-1		

Signature of inspector:

Date: 25/11/14

Name of inspector: ONOME OGBORU