



# Mojust Global Resources Ltd RC 808075

## OFFICE ADDRESS:

10 Hon. Gideon Street off Peter Odili Road Trans-Amadi, Port Harcourt. Tel: 08035593796, 08075694465

E-mail: [info@mojustglobal.com](mailto:info@mojustglobal.com), [mojustglobalresources@gmail.com](mailto:mojustglobalresources@gmail.com) Website: [www.mojustglobal.com](http://www.mojustglobal.com)



## CERTIFICATE OF VISUAL EXAMINATION

Client	CAVMONT LEASING NIGERIA LTD	CERTIFICATE NO.	BS/09-14/247
Equipment Owner/ Address	CAVMONT LEASING NIG LTD. PLOT 274 TRANS-AMADI, PORT HARCOURT	INSPECTOR QUALIFICATION	NIGERIA FACTORY ACT/ASNT LEVEL II
Location	CAVMONT BASE		
Inspection Date	29/09/2014	Next Inspection Date	28/03/2015

Description	BOX SKIP
Size (Metres)	LENGTH:3.01m WIDTH: 1.79m HEIGHT:1.22m
Equipment Identification	BS3-021
Tare Weight	1300Kg
Pay Load	5000Kg
Maximum Gross Weight	6300Kg

S/N	Item I.D No.	Qty	Items Description	SWL	Remark/Recommendation
1	Sling#: BS3-011/A	1	4Legs Wire Rope Sling 22mm dia . x 2.2m fitted with Quad Master Link Assembly at one end, c/w thimble eye on both end.	6.5 Tonnes @ 0-45°	Certified fit for Use
2	Shackle#: 01A/I-01A/4.	4	Safety Pin Bow Shackle (BS)	6.5 Tons	Certified fit for Use

### LOAD TEST DETAIL

UNIT	Tested By: BUREAU VERITAS	Certificate No:1059PL007/21	Test Date: 11/07
Sling	Tested By: GLOBAL LIFTING SERVICES(ABERDEEN)	Certificate No: 46777/0011	Test Date: 10/07

SPECIFICATION: DNV 2.7-1, BS EN13414-2, BS 13889	Equipment Type: N/A	Test Procedure: MG 53
NDT METHOD: Visual Inspection		Contrast Media: N/A
RESULTS: At the time of examination, no cracks, flaws or other defects likely to affect the safe use of the equipment was found. Ok for use	Pole Spacing: N/A	Indicator: Black N/A
STATUTORY INSTRUMENTS 1998 NO.2307, API Spec 9A, BS EN 13414-2, ASME Sec. V art 7 respectively. Lifting Operations and Lifting Equip. Regulation 1998. British Standard: DNV 2.7-1		

Signature of inspector:



Name of inspector: EMEKA JUDE

