



# Mojust Global Resources Ltd RC 808075

## OFFICE ADDRESS:

10 Hon. Gideon Street off Peter Odili Road Trans-Amadi, Port Harcourt. Tel: 08035593796, 08075694465

E-mail: info@mojustglobal.com, [mojustglobalresources@gmail.com](mailto:mojustglobalresources@gmail.com) Website: [www.mojustglobal.com](http://www.mojustglobal.com)



## CERTIFICATE OF VISUAL EXAMINATION

Client	CAVMONT LEASING NIGERIA LTD	CERTIFICATE NO.	C/10-14/262
Equipment Owner/ Address	CAVMONT LEASING NIG LTD. PLOT 274 TRANS-AMADI, PORT HARCOURT	INSPECTOR QUALIFICATION	NIGERIA FACTORY ACT/ASNT LEVEL II
Location	CAVMONT BASE		
Inspection Date	04/10/2014	Next Inspection Date	03/04/2015

Description	10FT CONTAINER
Size (Metres)	LENGTH: 2.43m WIDTH: 3.00m HEIGHT: 2.60m
Equipment Identification	DC10-288
Tare Weight	2720Kg
Pay Load	8000Kg
Maximum Gross Weight	10720Kg

S/N	Item LD No.	Qty	Items Description	SWL	Remark/Recommendation
1	Sling#: DC10-288/A	1	5Legs Wire Rope Sling 36/26mm dia. x 1.6/2.45m fitted with Quad Master Link Assembly at one end, c/w thimble eye on both end.	10.72 Tonnes @ 0-45°	Certified fit for Use
2	Shackle#: 88B-88E	4	Safety Pin Bow Shackle (Crosby)	8.5 Tons	Certified fit for Use

### LOAD TEST DETAIL

UNIT	Tested By: DET NORSKE VERITAS(DNV)	Certificate No: 309537	Test Date: 09/12
Sling	Tested By: UNIVERSAL INSPECTION LTD.(UIL)	Certificate No: 128023/25	Test Date: 07/09/12

SPECIFICATION: DNV 2.7-1, BS EN13414-2, BS 13889 NDT METHOD: Visual Inspection RESULTS: At the time of examination, no cracks, flaws or other defects likely to affect the safe use of the equipment was found. Ok for use	Equipment Type: N/A  Pole Spacing: N/A	Test Procedure: MG 53 Contrast Media: N/A Indicator: N/A
--	--	--

STATUTORY INSTRUMENTS 1998 NO.2307, API Spec 9A, BS EN 13414-2, ASME Sec. V art 7 respectively.  
Lifting Operations and Lifting Equip. Regulation 1998. British Standard: DNV 2.7-1

Signature of inspector:



Name of inspector: BETHEL IZUOGU