



# Mojust Global Resources Ltd RC 808075

## OFFICE ADDRESS:

10 Hon. Gideon Street off Peter Odili Road Trans-Amadi, Port Harcourt. Tel: 08035593796, 08075694465

E-mail: info@mojustglobal.com, [mojustglobalresources@gmail.com](mailto:mojustglobalresources@gmail.com) Website: www.mojustglobal.com



## CERTIFICATE OF VISUAL EXAMINATION

Client	CAVMONT LEASING NIGERIA LTD	CERTIFICATE NO.	OC/10-14/270
Equipment Owner/ Address	CAVMONT LEASING NIG LTD. PLOT 274 TRANS-AMADI, PORT HARCOURT	INSPECTOR QUALIFICATION	NIGERIA FACTORY ACT/ASNT LEVEL II, NSL
Location	CAVMONT BASE		
Inspection Date	18/10/2014	Next Inspection Date	17/04/2015

Description	10FT OFFSHORE CONTAINER
Size (Metres)	LENGTH: 2.97m WIDTH: 2.42m HEIGHT: 2.57m
Equipment Identification	DC10-322
Tare Weight	2720Kg
Pay Load	8000Kg
Maximum Gross Weight	10720Kg

S/N	Item ID No.	Qty	Items Description	SWL	Remark/Recommendation
1	Sling#: DC10-322A	1	5Legs Wire Rope Sling 36/26mm dia. x 2.5/1.6m fitted with Quad Master Link Assembly at one end, c/w thimble eye on both end.	10.72 Tonnes @ 0-45°	Certified fit for Use
2	Shackle#: 22B, 22C, 22D, 22E.	4	Safety Pin Bow Shackle (Crosby)	8.5 Tons	Certified fit for Use

### LOAD TEST DETAIL

UNIT	Tested By: LLOYD'S REGISTER	Certificate No: 309571	Test Date: 09/12
Sling	Tested By: UNIVERSAL INSPECTION LTD. (UIL)	Certificate No: 28032/59	Test Date: 21/09/12

SPECIFICATION: DNV 2.7-1, BS EN13414-2, BS 13889	Equipment Type: N/A	Test Procedure: MG 53
NDT METHOD: Visual Inspection		Contrast Media: N/A
RESULTS: At the time of examination, no cracks, flaws or other defects likely to affect the safe use of the equipment was found. Ok for use	Pole Spacing: N/A	Indicator: Black N/A
STATUTORY INSTRUMENTS 1998 NO.2307, API Spec 9A, BS EN 13414-2, ASME Sec. V art 7 respectively. Lifting Operations and Lifting Equip. Regulation 1998. British Standard: DNV 2.7-1		

Signature of inspector:



Name of inspector: EMEKA JUDE

