



Mojust Global Resources Ltd RC 808075

OFFICE ADDRESS:

10 Hon. Gideon St Off Peter Odili Rd T-Amadi, Port Harcourt. Tel: +(234)803 559 3796 + (234) 8075694479

E-mail: info@mojustglobal.com, mojustglobalresources@gmail.com Website: www.mojustglobal.com



CERTIFICATE OF VISUAL EXAMINATION

| | | | |
|-----------------------------|--|----------------------------|--------------------------------------|
| Client | CAVMONT LEASING NIGERIA LTD | CERTIFICATE NO. | MS/04-14/069 |
| Equipment Owner/ Address | CAVMONT LEASING NIG. Plot 274 Trans-Amadi, Port Harcourt. | INSPECTOR QUALIFICATION | NIGERIA FACTORY ACT/ASNT LEVEL II |
| Location | CAVMONT BASE | | |
| Inspection Date | 23/04/2013 | Next Inspection Date | 22/10/2014 |

| | |
|--------------------------|--|
| Description | MUD SKIP |
| Size (Metres) | LENGTH: 2.03m WIDTH: 1.78m HEIGHT: 1.40m |
| Equipment Identification | MC 640 |
| Tare Weight | 1230 Kg |
| Pay Load | 5770 Kg |
| Maximum Gross Weight | 7000 Kg |

| S/N | Item I.D No. | Qty | Items Description | SWL | Remark/Recommendation |
|-----|----------------------------------|-----|--|--------------------------|-----------------------|
| 1 | Sling#: RMC 640/1 | 1 | 4Legs Wire Rope Sling 20mm dia . x1.9m fitted with Quad Master Link Assembly at one end, c/w thimble eye on both end. | 7.0 Tonnes @ 0-45° | Certified fit for Use |
| 2 | Shackle#: 40/2,92/2,40/3,40/5 | 4 | Safety Pin Bow Shackle (BS6) | 4.75 Ton | Certified fit for Use |

LOAD TEST DETAIL

| | | | |
|-------|-------------------------------------|---------------------------|---------------------|
| UNIT | Tested By: Lloyd's Register | Certificate No: 218924 | Test Date: 27/06/09 |
| Sling | Tested By: Universal Inspection Ltd | Certificate No: 115078/53 | Test Date: 15/06/07 |

| | | |
|---|---------------------|-----------------------|
| SPECIFICATION: DNV 2.7-1, BS EN13414-2, BS EN 13889 | Equipment Type: N/A | Test Procedure: MG 53 |
| NDT METHOD: Visual Inspection | | Contrast Media: N/A |
| RESULTS: At the time of examination, no cracks, flaws or other defects likely to affect the safe use of the equipment was found. Ok for use | Pole Spacing: N/A | Indicator: N/A |

STATUTORY INSTRUMENTS 1998 NO.2307, API Spec 9A, BS EN 13414-2, ASME Sec. V art 7 respectively.
Lifting Operations and Lifting Equip. Regulation 1998. British Standard: DNV 2.7-1

Signature of inspector:

Name of inspector: ALADE TEMITOPE.

