



# Mojust Global Resources Ltd RC 808075

## OFFICE ADDRESS:

10 Hon. Gideon Street off Peter Odili Road Trans-Amadi, Port Harcourt. Tel: 08035593796, 08075694465

E-mail: info@mojustglobal.com, [mojustglobalresources@gmail.com](mailto:mojustglobalresources@gmail.com) Website: [www.mojustglobal.com](http://www.mojustglobal.com)



## CERTIFICATE OF VISUAL EXAMINATION AND MPI

Client	CAVMONT LEASING NIGERIA LTD	CERTIFICATE NO.	HHC/11-13/645
Equipment Owner/ Address	CAVMONT LEASING NIG. Plot 274 Trans-Amadi, Port Harcourt.	INSPECTOR QUALIFICATION	NIGERIA FACTORY ACT/ASNT LEVEL II
Location	CAVMONT BASE		
Inspection Date	05/11/2013	Next Inspection Date	04/05/2014

Description	HALF HEIGHT CONTAINER
Size (Metres)	LENGTH: 3.05m WIDTH: 2.44m HEIGHT: 1.32m
Equipment Identification	NHH10-007
Tare Weight	1750Kg
Pay Load	8500Kg
Maximum Gross Weight	10250Kg

S/N	Item I.D No.	Qty	Items Description	SWL	Remark/Recommendation
1	Sling#: NHH10-007/A	1	4Legs Wire Rope Sling 24mm dia . x2.6m fitted with Quad Master Link Assembly at one end, c/w thimble eye on both end.	15.5 Tonnes @ 0-45°	Certified fit for Use
2	Shackle#: 07B-E	4	Safety Pin Bow Shackle (Crosby)	8.5 Ton	Certified fit for Use

### LOAD TEST DETAIL

UNIT	Tested By: HECC	Certificate No: 5500/7	Test Date: 02/12
Sling	Tested By: UNIVERSAL INSPECTION LTD (UK)	Certificate No: 126977/07	Test Date: 02/12

SPECIFICATION: DNV 2.7-1, BS EN13414-2, BS EN 13889 NDT METHOD: Visual Inspection And MPI RESULTS: At the time of examination, no cracks, flaws or other defects likely to affect the safe use of the equipment was found. Ok for use	Equipment Type: Bar Magnet  Pole Spacing: 100mm	Test Procedure: MG 51  Contrast Media: White Contrast Aid  Indicator: Black Magnetic Ink
---	--	---

STATUTORY INSTRUMENTS 1998 NO.2307, API Spec 9A, BS EN 13414-2, ASME Sec. V art 7 respectively.  
Lifting Operations and Lifting Equip. Regulation 1998. British Standard: DNV 2.7-1

Signature of inspector:



Name of inspector: EMEKA JUDE.

