



# Mojust Global Resources Ltd RC 808075

## OFFICE ADDRESS:

10 Hon.Gideon Street Off Peter Odili Road Trans-Amadi, Port Harcourt. Tel: +(234)803 559 3796 +(234) 8032329144  
E-mail: [info@mojustglobal.com](mailto:info@mojustglobal.com); [mojustglobalresources@gmail.com](mailto:mojustglobalresources@gmail.com); Website: [www.mojustglobal.com](http://www.mojustglobal.com)



## CERTIFICATE OF VISUAL EXAMINATION

Client	CAVMONT LEASING NIG. LIMITED	CERTIFICATE NO.	MC/10-12/068
Equipment Owner/ Address	CAVMONT LEASING NIG. LIMITED	INSPECTOR QUALIFICATION	NIGERIA FACTORY ACT/ASNT LEVEL II
Location	CAVMONT BASE, PLOT 274 TRANS-AMADI PORT HARCOURT.		
Inspection Date	16/10/2012	Next Inspection Date	15/4/2013

Description	MINI CONTAINER		
Size (Metres)	LENGTH:1.91m	WIDTH: 1.58m	HEIGHT:2.89m
Equipment Identification	NRSM 028		
Designed Tare Weight	1980Kg		
Designed Safe Working Load	4500Kg		
Designed Gross Weight	6480Kg		

S/N	Item I.D No.	Qty	Items Description	SWL	Remark/Recommendation
1	Sling#: NRSM 028A	1	5Legs Wire Rope Sling 32/22mm dia. x 1.3/1.5m fitted with Quad Master Link Assembly at one end, the other end thimble eye.	6.48 Tonne @ O-45°	Certified fit for Use
2	Shackle#:28 B-E	4	Safety Pin Bow Shackle (BS)	6.5 Tons	Certified fit for Use

### LOAD TEST DETAIL

UNIT	Tested By: HECC LIMITED	Certificate No: NOT SEEN	Test Date: 8/9/2011	Proof Load Applied: 14220 KG
Sling	Tested By: UNIVERSAL INSPECTION LIMITED(UIL)	Certificate No: 126020/28	Test Date: 8/9/2011	Proof Load Applied: 11.4 Tonne/Leg

SPECIFICATION: DNV 2.7-1, BS EN 13414-2, BS EN 13889	Equipment Type: N/A	Test Procedure: MG 53
NDT METHOD: VISUAL INSPECTION	Pole Spacing: N/A	Contrast Media: N/A
RESULTS: At the time of examination, no cracks, flaws or other defects likely to affect the safe use of the equipment was found. <b>Ok for use</b>		Indicator: N/A

STATUTORY INSTRUMENTS 1998 NO.2307, API Spec 9A, BS 13414-2, ASME Sec. V art 7 respectively.  
Lifting Operations and Lifting Equip. Regulation 1998. British Standard: DNV 2.7-1

Signature of inspector:



Name of inspector: PATRICK SAMUEL

