



# Mojust Global Resources Ltd RC 808075

## OFFICE ADDRESS:

10 Hon.Gideon St Off Peter Odili Rd T-Amadi, Port Harcourt. Tel: +(234)803 559 3796 + (234) 8075694479

E-mail: [info@mojustglobal.com](mailto:info@mojustglobal.com), [mojustglobalresources@gmail.com](mailto:mojustglobalresources@gmail.com) Website: [www.mojustglobal.com](http://www.mojustglobal.com)



## CERTIFICATE OF VISUAL EXAMINATION

Client	CAVMONT LEASING NIGERIA LTD	CERTIFICATE NO.	OSCB/07-13/456
Equipment Owner/ Address	CAVMONT LEASING NIG. Plot 274 Trans-Amadi, Port Harcourt.	INSPECTOR QUALIFICATION	NIGERIA FACTORY ACT/ASNT LEVEL II
Location	CAVMONT BASE		
Inspection Date	13/07/2013	Next Inspection Date	12/01/2014

Description	12m STEP CHANGE BASKET		
Size (Metres)	LENGTH:12.0m	WIDTH: 1.22m	HEIGHT:1.12m
Equipment Identification	SC1228		
Tare Weight	3200Kg		
Pay Load	11500Kg		
Maximum Gross Weight	14700Kg		

S/N	Item I.D No.	Qty	Items Description	SWL	Remark/Recommendation
1	Sling#: SC1228A	1	4Legs Wire Rope Sling 32mm dia . x 4.2m fitted with Quad Master Link Assembly at one end, the other end thimble eye.	27.5Tonne @ O-45°	Certified fit for Use
2	Shackle#: 28B-E	4	Safety Pin Bow Shackle (Crosby)	9.5Tons	Certified fit for Use

### LOAD TEST DETAIL

UNIT	Tested By: HECC LTD	Certificate No:ACC5591/2	Test Date: 7/11
Sling	Tested By: UNIVERSAL INSPECTION LTD (UK)	Certificate No: 127838/02	Test Date: 7/12

SPECIFICATION: DNV 2.7-1, BS EN 13414-2, BS EN 13889 NDT METHOD: Visual Inspection RESULTS: At the time of examination, no cracks, flaws or other defects likely to affect the safe use of the equipment was found. Ok for use	Equipment Type: N/A  Pole Spacing: N/A	Test Procedure: MG 53 Contrast Media: N/A Indicator: N/A
STATUTORY INSTRUMENTS 1998 NO.2307, API Spec 9A, BS EN 13414-2, ASME Sec. V art 7 respectively. Lifting Operations and Lifting Equip. Regulation 1998. British Standard: DNV 2.7-1		

Signature of inspector:

Name of inspector: EMEKA JUDE..

