

OFFICE ADDRESS:

10 Hon. Gideon St Off Peter Odili Rd T-Amadi, Port Harcourt. Tel: +(234)803 559 3796 +(234) 8032329144

 E-mail: info@mojustglobal.com, mojustglobalresources@gmail.com Website:
www.mojustglobal.com


CERTIFICATE OF VISUAL EXAMINATION

| | | | |
|---------------------------------|---|--------------------------------|-----------------------------------|
| Client | CAVMONT LEASING NIGERIA LTD | CERTIFICATE NO. | GTF/10-12/045 |
| Equipment Owner/ Address | CAVMONT LEASING NIGERIA LTD | INSPECTOR QUALIFICATION | NIGERIA FACTORY ACT/ASNT LEVEL II |
| Location | Plot 274, Trans-Amadi Industrial layout, Port Harcourt. | | |
| Inspection Date | 04/10/2012 | Next Inspection Date | 03/04/2013 |

| | | | |
|-----------------------------------|-----------------------|--------------|-------------|
| Description | 600 GALLON TANK FRAME | | |
| Size (Metres) | LENGTH:2.02m | WIDTH: 2.02m | HEIGHT:1.6m |
| Equipment Identification | ST 820 | | |
| Designed Tare Weight | 2130Kg | | |
| Designed Safe Working Load | 4370Kg | | |
| Designed Gross Weight | 6500Kg | | |

| S/N | Item I.D No. | Qty | Items Description | SWL | Remark/Recommendation |
|-----|-------------------|-----|--|----------------------|-----------------------|
| 1 | Sling#: GL12683/3 | 1 | 4Legs Wire Rope Sling 22 mm dia . x 2.55m fitted with Quad Master Link Assembly at one end, the other end thimble eye. | 7Tonne @ O-45° | Certified fit for Use |
| 2 | Shackle#: 3/1-4 | 4 | Safety Pin Bow Shackle (BS) | 4.75Tons | Certified fit for Use |

LOAD TEST DETAIL

| | | | |
|--------------|---|-----------------------------|-----------------------|
| UNIT | Tested By: UNIVERSAL INSPECTION(UK) LTD | Certificate No:121675/154 | Test Date: 07/09/2009 |
| Sling | Tested By: GLOBAL LIFTING ABERDEEN | Certificate No: 12638/00003 | Test Date: 12/08/2004 |

| | | |
|---|--|---|
| SPECIFICATION: DNV 2.7-1, BS EN 13414-2, BS 3032 NDT METHOD: Visual Inspection RESULTS: At the time of examination, no cracks, flaws or other defects likely to affect the safe use of the equipment was found. Ok for use | Equipment Type: N/A Pole Spacing: N/A | Test Procedure: MG 53 Contrast Media: N/A Indicator: N/A |
|---|--|---|

STATUTORY INSTRUMENTS 1998 NO.2307, API Spec 9A, BS 13414-2, ASME Sec. V art 7 respectively.
 Lifting Operations and Lifting Equip. Regulation 1998. British Standard: DNV 2.7-1

Signature of inspector:

Name of inspector: PATRICK SAMUEL.

